

Labor and Materials

Copper	} Connection.....	in.	at	\$	
Lead						
Curb	} Cock Valve } T. S. & V. }	in.	at	\$	
Service Box						} Short 3½ x 4½ } Long 4½ x 5½ }
Old returned						
10 Ft.	3/4" in.					
	} Copper } Galv. Iron } Cast Iron }	in.	at	\$	
Nipples						} PLASTIC } Pipe at
Bushings						
Red'g	} Conplings.....	to	in.	at	\$	
Inc'g						
Union	in.	at	\$		
Meter	in.	at	\$		
Lead Joints	at	\$			
Leadite Joints	at	\$			
Hrs. Foreman	at	\$			
Hrs. Chauffeur	at	\$			
Hrs. Tapper	at	\$			
Hrs. Labor	at	\$			
Hrs. Labor	at	\$			
Hrs. Compressor	at	\$			
Compensation Ins.	\$				
Trucking	\$				
Builders Use of Water	\$				

St. 35
Pl. Daden
Ave. No. 33

Name of Owner _____

Labor and Mat'l. Report 19

● Curb Box

Main HOPE AV. Elev. of Main at tap.....

Gate at ● ● Gate at

● Curb Box

10' 3/4" PLASTIC
TO MAIN 10-28-16
TOP 10# 302.165-14