

### LABOR AND MATERIALS

Copper	}	Connection			\$
Lead					
Curb	}	Cock Valve T. S. & V.		in.	\$
Service Box					
Old returned	}	Short 3 1/2 x 4 1/2			\$
		Long 4 1/2 x 5 1/2			
		Buff. or Rdway			
Ft.	}	}		in.	\$
		Copper Galv Iron Cast Iron	Pipe at		
Nipples			in. at		\$
Bushings			to in. at		\$
Red'g Inc'g	}	Couplings		to in. at	\$
Union			in. at		\$
Meter			in. at		\$
Lead Joints			at		\$
Leadite Joints			at		\$
Hrs. Foreman			at		\$
Hrs. Chauffeur			at		\$
Hrs. Tapper			at		\$
Hrs. Labor			at		\$
Hrs. Labor			at		\$
Hrs. Compressor			at		\$
Compensation Ins.			at		\$
Trucking			at		\$
Builders Use of Water			at		\$
			at		\$
			at		\$
			at		\$
			at		\$
			at		\$

St. 36  
 Pr  
 Ave. No. 34

*Ogden*

---


Name of Owner \_\_\_\_\_

Tax ID# 302.16-1-14

---

Labor and Mat'l. Report Aug. 21 19 39

---

36  
  
35'0"      34'8"  
● Curb Box

---

	Main	Elev. of Main at tap
Gate at ●		● Gate at

---

● Curb Box