

LABOR AND MATERIALS

1	Copper	} Connection $\frac{3}{4}$ "	\$
1	Lead		\$
1	Curb	} Cock Valve T.S. & V. $\frac{3}{4}$ in.	\$
1	Service box		} { Short $3\frac{1}{2}$ x $4\frac{1}{2}$ Long $4\frac{1}{2}$ x $5\frac{1}{2}$ Buff or Rdway
28	Ft. $\frac{3}{4}$ in.	} { Copper G.I. C.I. } Pipe at	
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Inc'g }	Coupl'gs to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints	at	\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins. at \$	per C	\$
	Trucking		\$
	Pav't Patch		\$
	Tap by Giggord & Co.		\$
		7-22-63.	\$
	O'head		\$

Orchard St. Pl. Ave. No. 64

Name of Owner Ralph Chappa

Labor and Mat'l. Report July 22 1963

38' 2" 52' 10"

● Curb Box

6" C.I. Main Elev. of Main at tap $5\frac{1}{2}$ '

● Gate at ● Gate at

● Curb Box

TAX ID# 303.13-21-5

LSM-5C-3-10-61