

## Labor and Materials

Copper	}	Connection.....		\$	
Lead					
Curb	}	Cock	} in .....	\$	
		Valve			
		T. S. & V.			
Service Box	}	Short 3½ x 4½	} .....	\$	
Old returned		Long 4½ x 5½			
		Buff. or Rdway			
Ft. .... in.	}	Copper	} Pipe at .....	\$	
		Galv Iron			
		Cast Iron			
Nipples		in. at .....		\$	
Bushings		to .....	in. at .....	\$	
Red'g	}	Conplings .....	to .....	in. at .....	\$
Inc'g					
Union		in. at .....		\$	
Meter		in. at .....		\$	
Lead Joints		at .....		\$	
Leadite Joints		at .....		\$	
Hrs. Foreman		at .....		\$	
Hrs. Chauffeur		at .....		\$	
Hrs. Tapper		at .....		\$	
Hrs. Labor		at .....		\$	
Hrs. Labor		at .....		\$	
Hrs. Compressor		at .....		\$	
Compensation Ins.		.....		\$	
Trucking		.....		\$	
Builders Use of Water		.....		\$	
		.....		\$	
		.....		\$	
		.....		\$	
		.....		\$	
		.....		\$	
		.....		\$	
		.....		\$	
		.....		\$	

St.   
~~St.~~   
 Ave. No. Dec 24th

97 Park St

---

**Name of Owner**

---

**Labor and Mat'l. Report** 19

---

---

..... **Main**

Gate at ●

**Elev. of**  
Main at tap.....

● Gate at

---

● **Curb Box**

*Shut off at Curb - 7-28-76*

*Box + Rod Removed*

*Cut off ON House Side*