

### Labor and Materials

Copper	} Connection	3/4		\$
Lead				
Curb	{ Cock Valve	3/4 in.		\$
	T. S. & V.			
Service Box	{ Short 3/4 x 1/2			\$
Old returned	Long 4 1/2 x 3 1/2			
	Buff. or Rdway			
25 Ft.	{ Copper			\$
	Galv. Iron			
	Cast Iron			
	in. at			\$
Nipples				\$
Bushings	to	in. at		\$
Red'g	{ Couplings	to	in. at	\$
Inc'g				
Union	in. at			\$
Meter	in. at			\$
Lbs. Br. Stone	at			\$
Lbs. Sand	at			\$
Bags Cement	at			\$
Paving Brick	{ Mack			\$
	Red			
	Asphalt			
Lead Joints	at			\$
Leadite Joints	at			\$
Hrs. Foreman	at			\$
Hrs. Common Labor	at			\$
Hrs. Common Labor	at			\$
Hrs. Mason	at			\$
Hrs. Mason's Helper	at			\$
Hrs. Compressor	at			\$
Compensation Ins.				\$
Trucking				\$
Builders' Use of Water				\$
Total \$				.....

28-179

Labor and Material Report Dec 19 1929

~~6654~~ Peck Ave.

6" Main Elev of Main at tap 4 1/2

---

Gate at ● ● Gate at

---

● Curb Box

Frank Jenkins

TAX ID# 303.18-3-5