

### LABOR AND MATERIALS

Copper	}	Connection			\$
Lead					
Curb	}	Cock	} in.		\$
		Valve			
		T. S. & V.			
Service box	}	Short 3½ x 4½	}		
Old returned		Long 4½ x 5½			
					\$
Ft. 8 in.	}	Copper	} Pipe at		\$
		G. I.			
		G. I.			
Nipples		in. at			\$
Bushings		to in. at			\$
Red'g	}	} Coupl'gs	} to in. at		\$
Inc'g					
Union		in. at			\$
Meter		in. at			\$
					\$
Compound Joints		at			\$
Maintenance Foreman					\$
Hrs. Water Maint. Man-1		at			\$
Hrs. Water Maint. Man-2		at			\$
Hrs. Garage Foreman		at			\$
Hrs. Labor		at			\$
Hrs. Compressor		at			\$
					\$
Trucking					\$
Pav't Patch					\$
					\$
					\$
					\$
					\$

Pruyn's Island

St. \_\_\_\_\_  
Pt. \_\_\_\_\_  
Ave. No. \_\_\_\_\_

Murray

Name of Owner  
Claude Charlebois

---

Labor and Mat'l. Report 5 19 86

J-MAR

● Curb-Box GATE

---

	Elev. of
Main	Main at tap
Gate at ●	● Gate at

---

● Curb Box

8" COPPER

LSM-5C-6-1-67