

### LABOR AND MATERIALS

Copper	} Connection			\$		
Lead						
Curb	} Cock Valve	} in.			\$	
						T. S. & V.
Service box	} Short 3½ x 4½ Long 4½ x 5½ Buff or Rdway				\$	
Old returned						
Ft. <u>2</u> in.	} Copper G. I. C. I.	} Pipe at			\$	
Nipples						in. at
Bushings						to in. at
Red'g	} Coupl'gs	to in. at			\$	
Inc'g						
Union	in. at				\$	
Meter	in. at				\$	
Lead Joints	at				\$	
Compound Joints	at				\$	
Maintenance Foreman					\$	
Hrs. Water Maint. Man-1	at				\$	
Hrs. Water Maint. Man-2	at				\$	
Hrs. Garage Foreman	at				\$	
Hrs. Labor	at				\$	
Hrs. Compressor	at				\$	
Compensation Ins.	at \$	per C			\$	
Trucking					\$	
Pav't Patch					\$	
					\$	
					\$	
					\$	
O'head					\$	
					\$	

St.  
Pl.  
Ave. No. \_\_\_\_\_

Name of Owner  
Prign's Island  
Alena Walls Concrete - Clemente

Labor and Mat'l. Report April 19 86

● Curb Box

Main	Elev. of Main at tap. _____
Gate at ●	● Gate at

● Curb Box