Labor and Material Report	2 2 19 7
3H top at 180 1 16	West -
23°0°5°2″	р В Вох
6 Main	Eley of Main at tap
Gate at 1 fo main	● Gate at
Old tak skurt o	rh Box
Con the form	

(St)
230 RIDGE PI. Ave. No
Name of Owner
TAX 10 # 302.12-27-4
Labor and Mat'l. Report 19
PORCH 29'
Curb Box
CLEANOUT
Elev. of Main at tap
Gate at Gate at
Curb Box

RECEIVED

JAN 1 5 2018

City of Glens Falls W.W.T.P.

*	
Labor and Materials	
/ Copper Connection 3/4	. \$ 7.60
Curb Cock Valve P.S. & V.	\$ 2.27
Service Rox Short 31/4x11/4	
Old returned (Buff. or Rdway)	5.04
28 Ft. 3/4 in. Copper Gast Iron Pipe at	
	\$0.5
Red'g Couplingstoin. at	
Unionin. at	
Lbs. Br. Stone at	
Lbs. Sand at	\$
Bags Cement 'at	\$
Paving Brick Mack Red Asphalt	
Lead Joints at	
Leadite Joints at	\$ 6.25
5. Hrs. Common Labor at Tapper.	s 3 -
Hrs Mason's Helper at	
3Hrs. Compressor at	
Compensation Ins	63
Trucking	s28 —
To	ial \$60.97

LABOR AND MATERIALS

Copper Connection	\$
Curb Curb in	\$
Service box {Short 3-1/2 x 4-1/2 } Old returned {Long 4-1/2 x 5-1/2 }	_ \$
Ft in. $\left\{ egin{array}{ll} ext{Copper} \\ ext{G.l.} \\ ext{C.l.} \end{array} ight\}$ Pipe at	_ \$
Nipples in. at	_ \$
Bushings to in. at	_ \$
Red'g	
Inc'g	
Union in. at	_ \$
Meter in. at	_ \$
	_ \$
Compound Joints at	_ \$
Maintenance Foreman	_ \$
Hrs. Water Maint. Man - 1 at	_ \$
Hrs. Water Maint. Man - 2 at	\$
Hrs. Garage Foreman at	_ \$
Hrs. Labor at	_ \$
Hrs. Compressor at	_ \$
	_ \$
Trucking	_ \$
Pav't Patch	_ \$
	_ \$
	_ \$
	_ \$
	_ \$
	•