

LABOR AND MATERIALS

Copper	}	Connection.....	\$.....	
Lead					
Curb	{	Cock Valve T. S. & V. in.	\$.....	
Service Box					
Old returned	}	Short 3½x4½	\$.....	
		Long 4½x5½			
		Buffer Rdway			
Ft. in.	}	Copper	Pipe at.....	\$.....	
		Galv Iron			
		Cast Iron			
Nipples.....	in. at	\$.....			
Bushings.....	to	in. at	\$.....		
Red'g Inc'g	}	Couplings.....	to	in. at	\$.....
Union.....	in. at	\$.....			
Meter.....	in. at	\$.....			
Lead Joints at		\$.....			
Leadite Joints at		\$.....			
Hrs. Foreman at		\$.....			
Hrs. Chauffeur at		\$.....			
Hrs. Tapper at		\$.....			
Hrs. Labor at		\$.....			
Hrs. Labor at		\$.....			
Hrs. Compressor at		\$.....			
Compensation Ins.		\$.....			
Trucking		\$.....			
Builders Use of Water		\$.....			
		\$.....			
		\$.....			
		\$.....			
		\$.....			
		\$.....			
		\$.....			

St. Sanford
~~Pr.~~
 Ave. No. 39

Name of Owner _____

TAX ID # 30216-11-10

Labor and Mat'l. Report NOV 13 1940 19

..... Main Gage Av.

Gate at ●

Elev. of
Main at tap.....

● Gate at

● Curb Box

Sanford St.