

**Labor and Materials**

1	Copper } Connection		\$ 2.60
	Lead }		
1	Curb { Cock Valve } in.	9	\$ 2.30
	T-S & V }		
1	Service Box { Short 3/4x1 1/2 } in.	9	\$ 1.40
	Old returned { Long 1 1/2x5/8 } } Buff or Railway }		
23	Ft. in. { Copper Galv. Iron } Pipe at		\$ 6.10
	Cast Iron }		
	Nipples in. at		\$
	Bushings to in. at		\$
	Red'g } Couplings to in. at		\$
	Inc'g }		
	Union in. at		\$
	Meter in. at		\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick { Mack Red Asphalt } at		\$
	Lead Joints at		\$
	Leadite Joints at		\$
3	Hrs. Foreman at		\$ 1.85
1.4	Hrs. Common Labor at		\$ 5.69
	Hrs. Common Labor at		\$
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
	Hrs. Compressor at		\$
	Compensation Ins		\$ .20
	Trucking		\$ 1.00
	Builders' Use of Water Patch		\$ 5.00
Total \$			26.17

29-206  
**Labor and Material Report** Nov 15 19  
 45 Sanford St

4 Main Elev of Main at tap 5  
 Gate at TAX ID # 302.12-27-9 Gate at  
 Curb Box  
 old tap disconnected  
 23' to main  
 3/4" copper