

## LABOR AND MATERIALS

Copper	}	Connection			\$
Lead					
Curb	{	Cock Valve T. S. & V.			\$
			in.		
Service Box	{	Short 3½x4½ Long 4½x5½ Buff or Rdway			\$
Old returned					
Ft.	{	Copper Galv Iron Cast Iron			\$
in.			Pipe at		
Nipples					\$
Bushings					\$
Red'g Inc'g	}	Couplings			\$
			to	in. at	
Union					\$
Meter					\$
Lead Joints					\$
Leadite Joints					\$
Hrs. Foreman					\$
Hrs. Chauffeur					\$
Hrs. Tapper					\$
Hrs. Labor					\$
Hrs. Labor					\$
Hrs. Compressor					\$
Compensation Ins.					\$
Trucking					\$
Builders Use of Water					\$
					\$
					\$
					\$
					\$
					\$
					\$
					\$

St. \_\_\_\_\_  
 Pl. \_\_\_\_\_  
 Ave. No. 11

Sargent

Name of Owner  
Serrano

Labor and Mat'l. Report Aug 19 19-23

TAX ID # 302.8-2-46

Main Queensbury Elev. of Main at tap

Gate at ● ● Gate at

● Curb Box