

Labor and Materials

Copper	}	Connection.....	\$		
Lead					
Carb	}	Cock	in	\$	
		Valve			
		T. S. & V.			
Service Box	}	Short 3½ x 4½		\$	
Old returned		Long 4½ x 5½			
		Buff. or Rdway			
Ft. in.	}	Copper	Pipe at	\$	
		Galv Iron			
		Cast Iron			
Nipples	in. at		\$		
Bushings	to	in. at	\$		
Red'g	}	Conplings	to	in. at	\$
Inc'g					
Union	in. at		\$		
Meter	in. at		\$		
Lead Joints	at		\$		
Leadite Joints	at		\$		
Hrs. Foreman	at		\$		
Hrs. Chauffeur	at		\$		
Hrs. Tapper	at		\$		
Hrs. Labor	at		\$		
Hrs. Labor	at		\$		
Hrs. Compressor	at		\$		
Compensation Ins.			\$		
Trucking			\$		
Builders Use of Water			\$		
			\$		
			\$		
			\$		
			\$		
			\$		
			\$		
			\$		

St.
 Pl.
 Ave. No. 1

beard

Name of Owner

Labor and Mat'l. Report 9-10-18 19

33'0" 26'8"

● Curb Box

TAX ID # 309.12-9-19

..... Main
Elev. of Main at tap.....

Gate at ●
● Gate at

● Curb Box