

Labor and Materials

1	Lead Copper	Connection	\$	
1	Curb	Cock Valve T. S. & V. in	\$	
	Service Box	Short $3\frac{1}{2} \times 4\frac{1}{2}$	} Pipe at	\$	
	Old returned	Long $4\frac{1}{2} \times 5\frac{1}{2}$			
11	Ft.	Buff. or Rdway Copper Galv Iron Cast Iron in.	\$	
	Nipples	 in. at	\$	
	Bushings	 to in. at	\$	
	Red'g Inc'g	Conplings to in. at	\$	
	Union	 in. at	\$	
	Meter	 in. at	\$	
	Lead Joints		at	\$	
	Leadite Joints		at	\$	
	Hrs. Foreman		at	\$	
	Hrs. Chauffeur		at	\$	
	Hrs. Tapper		at	\$	
	Hrs. Labor		at	\$	
	Hrs. Labor		at	\$	
	Hrs. Compressor		at	\$	
	Compensation Ins.			\$	
	Tracking			\$	
	Builders Use of Water			\$	
				\$	
				\$	
				\$	
				\$	
				\$	

St. 7
 Pl.
 Ave. No. 7

Name of Owner
Schumerhorn

Labor and Mat'l. Report 1977

EAST of CRANDALL

● Curb Box

6" Main Elev. of Main at tap *5'*

Gate at ● ● Gate at
 TAX ID # *302.15.13.17*

● Curb Box
11' to main
3/4" COPPER
RENEWAL
TAP - 1978