

LABOR AND MATERIALS

Copper } Connection		\$
Lead } Cock		
	Valve	
	T. S. & V.	in. \$
Service box } Short 3 1/2 x 4 1/2		
Old returned } Long 4 1/2 x 5 1/2		
	Buff or Rdway	\$
9 Ft. in. } Copper		
	G. I.	
	C. I.	Pipe at \$
Nipples	in. at	\$
Bushings	to in. at	\$
Red'g } Coupl'gs	to in. at	\$
Inc'g }		
Union	in. at	\$
Meter	in. at	\$
Lead Joints	at	\$
Compound Joints	at	\$
Maintenance Foreman		\$
Hrs. Water Maint. Man-1	at	\$
Hrs. Water Maint. Man-2	at	\$
Hrs. Garage Foreman	at	\$
Hrs. Labor	at	\$
Hrs. Compressor	at	\$
Compensation Ins. at \$	per C.	\$
Trucking		\$
Pav't Patch		\$
Tap before PAVING		\$
1925?		\$
O'head		\$
		\$

St. _____
Pl. _____
Ave. No. 112

Name of Owner Sherman
CORNER CARTLAND ST.
Norman Robert.

Remeasured IN May 1957

Labor and Mat'l. Report Before Paving 1925

112

39'

29' 8"

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

TAX ID # 309.7-6-12

● Curb Box

LSM-5C-2-5 56