

29-213 167 SOUTH

Labor and Material Report 12 23 19 30

121 South St. (167)

Curb Box

6 Main Elev of Main at tap 4 1/2

Gate at 18' to main 3/4" copper Gate at

Curb Box

old taps disconnected

#167 12-5-86

36'6" 44' 2'

St. South Ave. No. 167

Name of Owner Hansen

Labor and Mat'l. Report 19 86

36' 43'9" Curb Box

Main Elev. of Main at tap

Gate at Gate at

Curb Box

21' 2" copper

TAX ID # 309.12-9-2

LSM-SC-6-1-67

Labor and Materials

1	Copper	Lead	Connection	314	\$ 2.60
1	Curb	Cock Valve	T.S. & V.	314 in.	\$ 2.30
	Service Box	Short 3 1/2 x 4 1/2	Long 4 1/2 x 5 1/2		\$ 1.40
	Old returned	Buff or Rdway			
18	Ft.	2	in.	Copper Galv. Iron Pipe at	\$ 4.77
	Nipples		in. at		\$
	Bushings		to in. at		\$
	Red'g Inc'g	Couplings		to in. at	\$
	Union		in. at		\$
	Meter		in. at		\$
	Lbs. Br. Stone		at		\$
	Lbs. Sand		at		\$
	Bags Cement		at		\$
	Paving Brick	Mack Red Asphalt		at	\$
	Lead Joints		at		\$
	Leadite Joints		at		\$
3	Hrs. Foreman		at		\$ 1.88
1.6	Hrs. Common Labor		at		\$ 6.50
	Hrs. Common Labor		at		\$
	Hrs. Mason		at		\$
	Hrs. Mason's Helper		at		\$
1	Hrs. Compressor		at		\$ 1.50
	Compensation Ins.		at \$		per C \$
	Trucking				\$ 22
	Builders' Use of Water				\$ 1.00
					\$ 25.00

2 in. service installed
 12/5/86 - Old service shut off
 but still connected to main
 Total \$ 47.17

LABOR AND MATERIALS

	Copper	Lead	Connection		\$
	Curb	Cock Valve	T. S. & V.		\$
	Service box	Short 3 1/2 x 4 1/2	Long 4 1/2 x 5 1/2		\$
	Old returned	Buff or Rdway			\$
21	Ft.	2	in.	Copper G.I. Pipe at	\$
	Nipples		in. at		\$
	Bushings		to in. at		\$
	Red'g Inc'g	Coupl'gs		to in. at	\$
	Union		in. at		\$
	Meter		in. at		\$
	Lead Joints		at		\$
	Compound Joints		at		\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man	1	at		\$
	Hrs. Water Maint. Man	2	at		\$
	Hrs. Garage Foreman		at		\$
	Hrs. Labor		at		\$
	Hrs. Compressor		at		\$
	Compensation Ins.		at \$		per C \$
	Trucking				\$
	Pav't Patch				\$
					\$
					\$
					\$
	O'head				\$