

77

Labor and Material Report 1928

3 Staple ST.

● Curb Box

6 Main Elev of Main at tap 44

Gate at ● ● Gate at

● Curb Box

Jay Kilby

3/4" Copper
25' to MAIN

Staple

Pl. Ave. No. 77

Name of Owner _____

Labor and Mat'l. Report 4/19/2012

● Curb Box

6" Main Elev. of Main at tap 4'

Gate at ● ● Gate at

TAX ID # 309.15-2-18

● Curb Box

22' 5" of 3/4" Copper

Labor and Materials

Copper	}	Connection			\$
Lead					
Curb	}	Cock Valve	in		\$
		T. S. & V.			
Service Box		Short 3 1/2 x 4 1/2			
Old returned		Long 4 1/2 x 5 1/2			\$
		Buff. or Rdway			
Ft.	}	Copper	Pipe at		\$
		Galv Iron			
		Cast Iron			
Nipples		in. at			\$
Bushings		to	in. at		\$
Red'g	}	Conplings	to	in. at	\$
Inc'g					
Union		in. at			\$
Meter		in. at			\$
Lead Joints		at			\$
Leadite Joints		at			\$
Hrs. Foreman		at			\$
Hrs. Chauffeur		at			\$
Hrs. Tapper		at			\$
Hrs. Labor		at			\$
Hrs. Labor		at			\$
Hrs. Compressor		at			\$
Compensation Ins.					\$
Trucking					\$
Builders Use of Water					\$
					\$
					\$
					\$
					\$
					\$
					\$

St. 77
 Pt. 83
 Ave. No. 83

S. Tap

Name of Owner
Mrs Guy Lilly

Labor and Mat'l. Report *Sept 28* 19*38*

Curb Box

.....Main
Elev. of Main at tap.....

Gate at ●
● Gate at

● Curb Box

Sept 28-38