

Labor and Materials

Copper	}	Connection.....	\$	
Lead					
Curb	}	Cock Valve T. S. & V.	in	\$	
Service Box					
Old returned					
	}	Short 3½ x 4½ Long 4½ x 5½ Buff. or Rdway	\$	
Ft.					
in.					
	}	Copper Galv Iron Cast Iron	Pipe at	\$	
Nipples					
in. at					
Bushings	to	in. at	\$		
Red'g Inc'g	}	Conplings	to	in. at	\$
Union					
Meter	in. at	\$			
Lead Joints at	\$				
Leadite Joints at	\$				
Hrs. Foreman at	\$				
Hrs. Chauffeur at	\$				
Hrs. Tapper at	\$				
Hrs. Labor at	\$				
Hrs. Labor at	\$				
Hrs. Compressor at	\$				
Compensation Ins.	\$				
Trucking	\$				
Builders Use of Water	\$				
.....	\$				
.....	\$				
.....	\$				
.....	\$				
.....	\$				
.....	\$				
.....	\$				
.....	\$				

Lot 21

St. TERRACOTTA
 Pt.
 Ave. No. 17

Name of Owner
Earl Dunn

Labor and Mat'l. Report 7-16-21 1919

21

17-0 21-3

● Curb Box

Main Elev. of Main at tap 5

Gate at ● ● Gate at

● Curb Box