

Labor and Materials

Copper	}	Connection.....	\$
Lead			
Carb	}	Cock in \$
		Valve	
		T. S. & V.	
Service Box	}	Short 3 1/2 x 4 1/2	\$
Old returned		Long 4 1/2 x 5 1/2	
		Buff. or Rdway	
21 Ft.	}	Copper	Pipe at \$
3 1/4 in.		Cast Iron	
Nipples in. at		\$
Bushings to in. at	\$
Red'g	}	Couplings..... to in. at
Inc'g			
Union in. at		\$
Meter in. at		\$
Lead Joints	at		\$
Leadite Joints	at		\$
Hrs. Foreman	at		\$
Hrs. Chauffeur	at		\$
Hrs. Tapper	at		\$
Hrs. Labor	at		\$
Hrs. Labor	at		\$
Hrs. Compressor	at		\$
Compensation Ins.			\$
Trucking			\$
Builders Use of Water			\$
			\$
			\$
			\$
			\$
			\$
			\$
			\$
			\$

St: 29
 Pt:
 Ave. No. 27

TERRA COSTA

Name of Owner
Ormsby

Labor and Mat'l. Report 11-12-20 19

29

```

graph TD
    Main[Main] --- Gate[Gate]
    Main --- Branch[ ]
    Branch --- 25A[25-A]
    Branch --- 16A[16-A]
    25A --- CB[Carb Box]
    16A --- CB

```

Main		Elev. of Main at tap.....
Gate at • <i>3/4" copper</i>	• Gate at <i>21 to MAIN</i>	

● Carb Box

1998 - RENEWAL TAP

TAX ID # 302.12-10-5