

LABOR AND MATERIALS

1. Copper Lead	{ Connection <u>3/4"</u>	\$ 2.76
1. Curb	{ Cock Valve } <u>3/4 in.</u>	\$ 3.49
	T. S. & V.	
1. Service box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buffer Rdway }	\$ 4.74
1.6 Ft. <u>3/4 in.</u>	{ Copper Pipe at <u>38</u>	\$ 6.08
	{ C-I. C-I. }	
Nipples	in. at	\$
Bushings	to in. at	\$
Red'g Inc'g	Coupl'gs to in. at	\$
Union	in. at	\$
Meter	in. at	\$
Lead Joints at		\$
Compound Joints at		\$
2 Hrs. Water Maint. Man-1 at	<u>5 man 1.59</u>	\$ 3.18
6 Hrs. Water Maint. Man-2 at	<u>1.24</u>	\$ 9.92
1.8 Hrs. Labor at	<u>1.13</u>	\$ 20.34
Hrs. Labor at		\$
Hrs. Compressor at		\$
Compensation Ins. at	\$ <u>4.406</u> per C	\$ 1.47
Trucking		\$ 1.00
Pav't Patch		\$ 9.90
Tap by <u>J.F.F.O.R.D. 6-25-53</u>		\$
O'head		\$
		\$ 62.98

52-98

3344

Chapter 30 pdf

2 / 8

Third

Name of Owner Burlett

Labor and Mat'l. Report June 25 1953

St.

~~Pl.~~

Ave. No. 54

4" Main

Gate at ●

Elev. of Main at tap 4'

Gate at ●

3/4 copper 16' to main

● Curb Box

TAX ID # 309.11-11-8

LSM-5C 5 15-48