

✓

St. Third
 Ave. No. 84

Name of Owner
Geo. Delano.

Labor and Mat'l. Report Nov. 21 1957

#84
 40' 2"
 34' 7"
 ● Curb Box

6" Main Elev. of Main at tap 8'

Gate at ● ● Gate at

3/4" Copper 26' to main

● Curb Box

TAX ID # 309.11.9-1

LSM-5C-2-5 56

159

?

St. Third
 Ave. No. 86

Name of Owner
Sweet

Labor and Mat'l. Report Nov 19 1948

38' 10"
 49' 10"
 ● Curb Box

6" Main Elev. of Main at tap 6

Gate at ● ● Gate at

3/4" Copper 26' to main

● Curb Box

LSM-5C B 15-48 This Tap in Conduit House

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$
1	Curb	Cock Valve T. S. & V.	3/4" in.	\$
1	Service box	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$
	Old returned			\$
26	Ft. 3/4 in.	Copper G. I. C. I.	Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by Gifford & Co.			\$
	11-27-57			\$
	O'head			\$
				\$

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$	2.94
1	Curb	Cock Valve T. S. & V.	3/4" in.	\$	3.71
1	Service box	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$	5.90
	Old returned			\$	
26	Ft. 3/4 in.	Copper G. I. C. I.	Pipe at	\$	7.80
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Coupl'gs to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
1/2	Hrs. Water Maint. Man-1	at	1.12	\$	56
6	Hrs. Water Maint. Man-2	at	1.02	\$	6.12
17	Hrs. Labor	at	.91	\$	15.47
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.	at \$ 7.00 per C		\$	49
	Trucking			\$	1.49
	Pav't Patch			\$	
	Tap by M. J. ...			\$	
	O'head			\$	
				\$	43.99