

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$
1	Curb	Cock Valve T.S. & V.	3/4 in.	\$
1	Service box	Short 3 1/2 x 4 1/2		
	Old returned	Long 4 1/2 x 5 1/2		
		Buff or Rdway		\$
9	Ft. 3/4 in.	Copper Pipe		\$
		<del>G.I.</del>		
		<del>C.I.</del>		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pay't Patch			\$
	Tap by Gissordt Co.			\$
	12-3-58			\$
	O'head			\$

St. Thompson Ave. No. 6  
 Pl. 6  
 Name of Owner Baynton  
 Labor and Mat'l. Report Dec. 3 1958

6" Main      Elev. of Main at tap 5 1/2'

Gate at •      • Gate at

3/4" COPPER      9' to MAIN

• Curb Box

TAX ID# 302.15-8-17

LSM-SC-2-1-54