

Labor and Materials

Copper	}	Connection	\$	
Lead			\$	
Curb	}	Cock Valve T. S. & V. in	\$	
Service Box			}	Short 3 1/2 x 4 1/2	\$
Old returned				Long 4 1/2 x 5 1/2	\$
		Buff. or Rdway			
23 Ft.	}	Copper- Galv Iron Cast Iron	in. Pipe at	\$	
Nipples			in. at	\$	
Bushings			to in. at	\$	
Red'g Inc'g	}	Conplings	to in. at	\$	
Union			in. at	\$	
Meter	in. at	\$			
Lead Joints	at	\$			
Leadite Joints	at	\$			
Hrs. Foreman	at	\$			
Hrs. Chauffeur	at	\$			
Hrs. Tapper	at	\$			
Hrs. Labor	at	\$			
Hrs. Labor	at	\$			
Hrs. Compressor	at	\$			
Compensation Ins.		\$			
Tracking		\$			
Builders Use of Water		\$			
		\$			
		\$			
		\$			
		\$			
		\$			

97
 Ft.
 Ave. No. 33
 28

Thompson

Name of Owner
 TAX ID # 302.16-4.16

Labor and Mat'l. Report Nov. 18 19 16

33

21'2" 24'6"

● Curb Box

6 Main
Elev. of
Main at tap.....

Gate at ● ● Gate at

23' to main

● Curb Box