	St. PI? Ave. No
Name of Owner	
Labor and Mat'l. Report	19
CLEAR	-
ONE FOUT	BEHIND
una Rop	Curb Box
Main	Elev. of Main at tap
Gate at	• Gate at
	Curb Box

	*
	0
-1	DI CONT
Thomson	PI. Ave. No.
Name of Owner	
TAX #D# 302	1/2-2-5
11711 + 0 000	,102
Labor and Mat'l. Report	lov 23 1925
i Po	reh /
-4-	7
3710	136.8"
	Curb Box
6 Main	Elev. of Main at tap
Gate at •	• Gate at
Sate at 1	

	Curb Box
	Guis Box
	-0.040 <u>-</u>
L. M-5C-2-1-54	*
20	

LABOR AND MATERIALS

Copper } Connection	\$
Curb Curb Cock Valve T.S. & V.	\$
Service box Short 3-1/2 x 4-1/2 Old returned Long 4-1/2 x 5-1/2	
$-$ Ft. $-$ in. $\left\{ egin{array}{ll} \text{Copper} \\ \text{C.I.} \end{array} \right\}$ Pipe at $-$	\$
Nipples in, at	. \$
Bushings to in. at	_ \$
Red'g	
Inc'g	
Union in. at	\$
Meter in, at	\$
	. \$
Compound Joints at	. \$
Maintenance Foreman	\$
Hrs. Water Maint. Man - 1 at	\$
Hrs. Water Maint. Man - 2 at	s
Hrs. Garage Foreman at	\$
Hrs. Labor at	\$
Hrs. Compressor at	\$
	. \$
Trucking	\$
Pav't Patch	117407
	\$
	\$
4. — 4 4. — — — — — — — — — — — — — — —	\$
	\$

LABOR AND MATERIALS
2/- //
Copper Connection 5
1 (Cock)3/2
Curb Valve T.S. & V. 4 in. \$
Service box Short 314 x 414 Long 41/2 x 51/4
Buff or Rdway \$
Ft. in. Copper Pipe at \$
C. I.
Nipples in at \$
Bushings to in at \$
Red'g Coupl'gs to 3/4 in. at \$
Union in, at \$
Meterin. at\$
Lead Joints at \$
Compound Joints at \$
Maintenance Foreman \$
Hrs. Water Maint. Man-1 at \$
Hrs. Water Maint. Man-2 at \$
4 Hrs. Labor— at S
Hrs. Compressor at
Compensation Ins. at \$ per C \$
Pav't Patch \$
\$\$
\$
\$