


Labor and Materials

1..	Copper	} Connection ^{3/4}	\$ 96
1..	Lead			
1..	Curb	} Cock Valve T.S.&V. ^{3/4} in	\$ 1.33
1..	Service Box Old returned		} Short ^{3/4} x ^{1 1/2} Long ^{4 1/2} x ^{5 1/2} Butt. or Flange
9..	Ft. ^{3/4} in.	} Copper Galv. Iron Cast Iron		Pipe at ¹⁵
	Nipples			in. at
	Bushings		to .. in. at	\$
	Red'g Inc'g	} Couplings to .. in. at	\$
	Union			in. at
	Meter		in. at	\$
	Lbs. Br. Stone		at	\$
	Lbs. Sand		at	\$
	Bags Cement		at	\$
	Paving Brick	} Mack Red Asphalt	at	\$
	Lead Joints			at
	Leadite Joints		at	\$
	Hrs. Foreman		at	\$
	Hrs. Common Labor		at	\$
	Hrs. Common Labor		at	\$
	Hrs. Mason		at	\$
	Hrs. Masons Helper		at	\$
	Hrs. Compressor		at	\$
	Compensation Ins			\$
	Trucking			\$
	Builders Use of Water	Patch		\$
Total \$			

Labor and Material Report

103 36 28
 Nov 16 1936

9 Union St
 Potter



4" galv. Main

Elev. of Main at tap 24

Gate at • 9' to main Gate at •

● Curb Box

Old tap shut off

This House Razed.
 1965

SH