## LABOR AND MATERIALS

Copper Connection	. \$
Curb Cock Valve In	. \$
Service box Old returned Short 3½ x 4½ Long 4½ x 5½ Buff or Rdway	. \$
Ft. in. Copper G. I. Pipe at Pipe at	\$
Nipplesin. at	\$
Bushings to in. at	
Red'g Coupl'gstoin. at	\$
Unionin. at	. \$
Meterin. at	. \$
Lead Joints at	. \$
Compound Joints at	
Maintenance Foreman	
Hrs. Water Maint. Man-1 at	\$
Hrs. Water Maint. Man-2 at	\$
Hrs. Garage Foremanat	. \$
Hrs. Laborat	
Hrs, Compressor at	
Compensation Ins. at \$per C	
Trucking	
Pav't Patch	\$
	. \$
	. \$
T sel	. S
O'head	\$
	\$

,	EC
Union	St. Pl. Ave. No
Name of Owner	L. Hal School
STATISTICS TO SELECT	6
Labor and Mat'l. Report	Mar 19/6
_	
266"	30.6"
delete	
	Curb Box
Main	Elev. of Main at tap
Gate at •	• Gate at
	(4
	• Curb Box
This Ho	use Razed.
	1965
LSM-5C-9-10-61	