

LABOR AND MATERIALS

Copper	} Connection		\$
Lead		} <i>Wheel Valve.</i>	
Curb			in.
	} T.S. & V.		
1 Service box	} { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway }		\$
Old returned			
			\$
Ft. in.	} { Copper G.I. C.I. }	Pipe at	\$
Nipples		in. at	\$
Bushings		to in. at	\$
Red'g	} Coupl'gs	to in. at	\$
Inc'g			
Union	in. at		\$
Meter	in. at		\$
Lead Joints	at		\$
Compound Joints	at		\$
Maintenance Foreman			\$
Hrs. Water Maint. Man-1	at		\$
Hrs. Water Maint. Man-2	at		\$
Hrs. Garage Foreman	at		\$
Hrs. Labor	at		\$
Hrs. Compressor	at		\$
Compensation Ins. at \$	per C		\$
Trucking			\$
Pav't Patch			\$
			\$
			\$
O'head			\$
			\$

St. _____
-Pl- _____
Ave. No. 7

Union

Name of Owner _____

TAX ID # 302.20-12-11

Measured in

Labor and Mat'l. Report May 6 1960.

Main Elev. of
Main at tap

Gate at ● ● Gate at

5th.

● Curb Box

Buffalo Box.

LSM-5C-2-5-56