

**Labor and Materials**

.....Copper } Connection.....	.....\$.....
.....Lead } .....	.....\$.....
.....Curb { Cock } .....	.....\$.....
.....Valve } .....	.....\$.....
.....T.S.&V. } .....	.....\$.....
.....Service Box { Short 3 1/2 x 4 1/2 } .....	.....\$.....
.....Old returned { Long 4 1/2 x 5 1/2 } .....	.....\$.....
.....Buff, or Rdway } .....	.....\$.....
.....Ft.....In. { Copper } Pipe at .....	.....\$.....
.....Galv. Iron } .....	.....\$.....
.....Cast Iron } .....	.....\$.....
.....Nipples .....in. at .....	.....\$.....
.....Bushings .....to .....in. at.....	.....\$.....
.....Red'g } Couplings.....to.....in.at.....	.....\$.....
.....Inc'g } .....	.....\$.....
.....Union.....in. at .....	.....\$.....
.....Meter.....in. at .....	.....\$.....
.....Lbs. Br. Stone at .....	.....\$.....
.....Lbs. Sand at .....	.....\$.....
.....Bags Cement at .....	.....\$.....
.....Paving Brick { Mack } at .....	.....\$.....
.....Red } .....	.....\$.....
.....Asphalt } .....	.....\$.....
.....Lead Joints at .....	.....\$.....
.....Leadite Joints at .....	.....\$.....
.....Hrs. Foreman at .....	.....\$.....
.....Hrs. Common Labor at .....	.....\$.....
.....Hrs. Common Labor at .....	.....\$.....
.....Hrs. Mason at .....	.....\$.....
.....Hrs. Masons Helper at .....	.....\$.....
.....Hrs. Compressor at .....	.....\$.....
.....Compensation Ins .....	.....\$.....
.....Trucking .....	.....\$.....
.....Builders Use of Water .....	.....\$.....
Total \$.....	

6 1/2 - Wait #8R (Hunting)

House Razed  
Curb box removed  
1970

#8  
10

see below



Main

Elev of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

