

LABOR AND MATERIALS

Copper	}	Connection	-----	\$	-----
Lead					
Curb	}	Cock Valve	-----	in.	\$
		T. S. & V.			
Service Box					
Old returned	}	Short 3 1/2 x 4 1/2	-----	\$	-----
		Long 4 1/2 x 5 1/2			
		Buff. or Rdway			
Ft. -----	}	Copper	Pipe at -----	\$	-----
in. -----		Galv Iron			
		Cast Iron			
Nipples	in. at -----	\$	-----		
Bushings	to -----	in. at -----	\$	-----	
Red'g	}	Couplings	to -----	in. at -----	\$
Inc'g					
Union	in. at -----	\$	-----		
Meter	in. at -----	\$	-----		
Lead Joints	at -----	\$	-----		
Leadite Joints	at -----	\$	-----		
Hrs. Foreman	at -----	\$	-----		
Hrs. Chauffeur	at -----	\$	-----		
Hrs. Tapper	at -----	\$	-----		
Hrs. Labor	at -----	\$	-----		
Hrs. Labor	at -----	\$	-----		
Hrs. Compressor	at -----	\$	-----		
Compensation Ins.	-----	\$	-----		
Trucking	-----	\$	-----		
Builders Use of Water	-----	\$	-----		
		\$	-----		
		\$	-----		
		\$	-----		
		\$	-----		
		\$	-----		
		\$	-----		
		\$	-----		
		\$	-----		
		\$	-----		
		\$	-----		

St. 19-27
 Pt.
 Ave. No. 13-19

Warren

Name of Owner
Fulton Theater Corp.

Labor and Mat'l. Report 10-14-21 19

10" Main Elev. of Main at tap 5 1/2'

Gate at ● ● Gate at

● Curb Box

6" tap

10/2022 - not on map