

LABOR AND MATERIALS

1	Copper Lead	Connection	1 1/2"	\$	
1	Curb	Cock Valve T. S. & V.	1/2 in.	\$	
1	Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$	
18	Ft. 1/2 in.	Copper G. I. G. I.	Pipe at	\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Coupl'gs to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man-1	at		\$	
	Hrs. Water Maint. Man-2	at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.	at \$ per C		\$	
	Trucking			\$	
	Pav't Patch			\$	
	Tap by Gissord			\$	
	5 Co. 1 8-17-61.			\$	
	O'head			\$	
				\$	

St. Warren  
Pl. 28  
Ave. No. 28

Name of Owner Giacomo DeSignore  
Globe Hotel.

Labor and Mat'l. Report July 31 1961.

Elev. of Main at tap 5'

10" Main

Gate at ● Gate at ●

18' to main

● Curb Box

not on map 10/2022

LSM-BC-3-10-61