

LABOR AND MATERIALS

Copper	}	Connection	-----	\$
Lead				
Curb	}	Cock Valve	----- in.	\$
		T. S. & V.		
Service Box	}	Short 3/2x4 1/2	-----	\$
Old returned		Long 4 1/2x5 1/2	-----	
		Buff. or Rdway		
Ft.	}	Copper	-----	\$
in.		Galv Iron	-----	
		Cast Iron	-----	
Nipples		in. at	-----	\$
Bushings		to in. at	-----	\$
Red'g	}	Couplings	----- to in. at	\$
Inc'g				
Union		in. at	-----	\$
Meter		in. at	-----	\$
Lead Joints		at	-----	\$
Leadite Joints		at	-----	\$
Hrs. Foreman		at	-----	\$
Hrs. Chauffeur		at	-----	\$
Hrs. Tapper		at	-----	\$
Hrs. Labor		at	-----	\$
Hrs. Labor		at	-----	\$
Hrs. Compressor		at	-----	\$
Compensation Ins.			-----	\$
Trucking			-----	\$
Builders Use of Water			-----	\$
			-----	\$
			-----	\$
			-----	\$
			-----	\$

St. 38
~~St.~~
 Ave. No. 30-32

WARRON

Name of Owner
Lemon Thomson Realty Corp.

Labor and Mat'l. Report 19

38

 Curb Box

10 Main
Elev. of Main at tap 4

Gate at ●
● Gate at

TAX ID # 303.17-16-15

● Curb Box