

LABOR AND MATERIALS

Copper	}	Connection			\$
Lead					
Curb	{	Cock Valve T. S. & V.			\$
			in.		
Service Box	{	Short 3½x4½ Long 4½x5½ Buffer Rdway			\$
Old returned					
Ft.	}	Copper Galv Iron Cast Iron			\$
in.				Pipe at	
Nipples		in. at			\$
Bushings		to	in. at		\$
Red'g Inc'g	}	Couplings			\$
			to	in. at	
Union		in. at			\$
Meter		in. at			\$
Lead Joints at					\$
Leadite Joints at					\$
Hrs. Foreman at					\$
Hrs. Chauffeur at					\$
Hrs. Tapper at					\$
Hrs. Labor at					\$
Hrs. Labor at					\$
Hrs. Compressor at					\$
Compensation Ins.					\$
Trucking					\$
Builders Use of Water					\$
					\$
					\$
					\$
					\$
					\$

St. 78
 Pl.
 Ave. No. 50

Warren

Name of Owner
Mrs Cool

Labor and Mat'l. Report *Feb 18* 19*44*

Main Elev. of
Main at tap

Gate at ● ● Gate at

● Curb Box

10/22
not on map