

LABOR AND MATERIALS

1	Copper Lead	Connection	1"	\$
1	Curb	Cock Valve T.S. & V.	1 in.	\$
1	Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway		\$
9	Ft. 1 in.	Copper G.I. C.I. Pipe at		\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints at			\$
	Compound Joints at			\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1 at			\$
	Hrs. Water Maint. Man-2 at			\$
	Hrs. Garage Foreman at			\$
	Hrs. Labor at			\$
	Hrs. Compressor at			\$
	Compensation Ins. at \$	per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by Gifford & Co.			\$
	8-9-60.			\$
	O'head			\$
				\$

St. Warren  
 Pl. 106-108  
 Ave. No. 110

Name of Owner Esso Service Station

Labor and Mat'l. Report Aug. 9 1960

10" Main Elev. of Main at tap 5 1/2'

Gate at • Gate at

1" COPPER

• Curb Box

#106  
 TAX ID# 363.17-19-19