

Labor and Materials

Copper	Connection.....	\$.....	
Lead			
Curb	Cock Valve T. S. & V. } in.....	\$.....	
Service Box	Sheet 2 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2 } Buff or Rd wax }	\$.....	
Old returned			
19 Ft. 3/4 in.	Copper } Galv Iron } Pipe at.....	\$.....	
	Cast Iron }	\$.....	
Nipples	in. at.....	\$.....	
Bushings	to..... in. at.....	\$.....	
Red'g Inc'g	Conplings to..... in. at.....	\$.....	
Union	in. at.....	\$.....	
Meter	in. at.....	\$.....	
Lead Joints	at.....	\$.....	
Leadite Joints	at.....	\$.....	
Hrs. Foreman	at.....	\$.....	
Hrs. Chauffeur	at.....	\$.....	
Hrs. Tapper	at.....	\$.....	
Hrs. Labor	at.....	\$.....	
Hrs. Labor	at.....	\$.....	
Hrs. Compressor	at.....	\$.....	
Compensation Ins.	\$.....	
Trucking	\$.....	
Builders Use of Water	\$.....	
		\$.....	
		\$.....	
		\$.....	
		\$.....	
		\$.....	
		\$.....	

St. *E 29*
Pl. *26*
Ave. No. *26*

Name of Owner
Probusco

TAX ID # 302.20-18-27

Labor and Mat'l. Report 19

Measure in Curb Box

In Sidewalk

4..... Main Elev. of Main at tap... 5

Gate at *3/4" copper* *19' to main* Gate at

44'

Curb Box For 26' E. Was Washington

24' E. Washington