

LABOR AND MATERIALS

1 Copper Lead Connection $\frac{1}{2}$ " \$

1 Curb { Cock Valve } $\frac{5}{8}$ in. \$

1 Service Box { T.S. & V. } \$

Old returned { Short $3\frac{1}{2} \times 4\frac{1}{2}$ } ? \$

{ Long $4\frac{1}{2} \times 5\frac{1}{2}$ } \$

{ Buff. or Rdway } \$

23 Ft. $\frac{3}{4}$ in. { Copper Galv Iron Cast Iron } Pipe at \$

Nipples in. at \$

Bushings to in. at \$

Red'g Inc'g { Couplings } to in. at \$

Union in. at \$

Meter in. at \$

Lead Joints at \$

Leadite Joints at \$

Hrs. Foreman at \$

Hrs. Chauffeur at \$

Hrs. Tapper at \$

Hrs. Labor at \$

Hrs. Labor at \$

Hrs. Compressor at \$

Compensation Ins. \$

Trucking \$

Builders Use of Water \$

\$

\$

\$

\$

\$

\$

St. **27**
 Pl. **21**
 Ave. No. **21**

William
 Name of Owner **Malatsky**

Labor and Mat'l. Report **Nov. 17** 19**17**

27
 25.13"
 41.5"
 Curb Box

TAX ID # 302.16-17-13

4" Main Elev. of Main at tap

Gate at ● Gate at ●

23' to main

● Curb Box

CLEANOUT LOCATED
 BY LEFT CORNER OF OLD.
 BETWEEN 2 BALLISTON