

LABOR AND MATERIALS

1	Copper Lead	} Connection $\frac{3}{4}$ "	\$
1	Curb		} Cock Valve T.S. & V. $\frac{3}{4}$ in. oriseat.
1	Service box Old returned	} { Short $3\frac{1}{2}$ x $4\frac{1}{2}$ Long $4\frac{1}{2}$ x $5\frac{1}{2}$ Buff or Rdway	
10	Ft. $\frac{3}{4}$ in.		} { Copper C.I. C.I. } Pipe at
	Nipples	in. at	
	Bushings	to in. at	\$
	Red'g Inc'g	} Coupl'gs. to in. at	\$
	Union		in. at
	Meter	in. at	\$
	Lead Joints	at	\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins. at \$	per C	\$
	Trucking		\$
	Pav't Patch		\$
	Tap by Gifford & Co.		\$
	9-29-66.		\$
	O'head		\$

St. William
 PL Manitta
 Ave. No. 28

Name of Owner _____

Labor and Mat'l. Report Sept. 29 1966

24" Main Elev. of Main at tap 46'

Gate at ● ● Gate at

10' to main

● Curb Box

TAX ID # 302.16-15-40

LSM-BC-3-10-61