

LABOR AND MATERIALS

_____	Copper	} Connection _____	\$ _____
_____	Lead		
_____	Curb	} _____ in. _____	\$ _____
	Cock		
	Valve T.S. & V.		
_____	Service box	{ Short 3-1/2 x 4-1/2 }	\$ _____
_____	Old returned		{ Long 4-1/2 x 5-1/2 }
_____	Ft. _____ in.	{ Copper G.I. C.I. }	Pipe at _____ \$ _____
_____	Nipples _____		in. at _____ \$ _____
_____	Bushings _____		to _____ in. at _____ \$ _____
_____	Red'g		
_____	Inc'g		
_____	Union _____	in. at _____	\$ _____
_____	Meter _____	in. at _____	\$ _____
_____			\$ _____
_____	Compound Joints at _____		\$ _____
_____	Maintenance Foreman _____		\$ _____
_____	Hrs. Water Maint. Man - 1 at _____		\$ _____
_____	Hrs. Water Maint. Man - 2 at _____		\$ _____
_____	Hrs. Garage Foreman _____	at _____	\$ _____
_____	Hrs. Labor _____	at _____	\$ _____
_____	Hrs. Compressor at _____		\$ _____
_____			\$ _____
_____	Trucking _____		\$ _____
_____	Pav't Patch _____		\$ _____
_____			\$ _____
_____			\$ _____
_____			\$ _____

WINDY RIDGE St. 2
Pt. 2
Ave. No. 2

Name of Owner
BARBARA FIORE

Labor and Mat'l. Report ~~**~~ 12-2001

A = 35 FT
B = 52 FT

● Curb Box
_____ Main Elev. of Main at tap _____

Gate at ● Gate at ●
TAX ID # 303.9-8-1

