

LABOR AND MATERIALS

Copper } Connection _____ \$ _____	
Lead } _____ \$ _____	
Curb } Cock Valve } _____ in. _____ \$ _____	
} T.S. & V. }	
3/4" Service box { Short 3-1/2 x 4-1/2 } _____ \$ _____	
Old returned { Long 4-1/2 x 5-1/2 }	
_____ Ft. _____ in. { Copper } Pipe at _____ \$ _____	
} G.I. }	
} C.I. }	
_____ Nipples _____ in. at _____ \$ _____	
_____ Bushings _____ to _____ in. at _____ \$ _____	
_____ Red'g _____	
_____ Inc'g _____	
_____ Union _____ in. at _____ \$ _____	
_____ Meter _____ in. at _____ \$ _____	
_____ Compound Joints at _____ \$ _____	
_____ Maintenance Foreman _____ \$ _____	
_____ Hrs. Water Maint. Man - 1 at _____ \$ _____	
_____ Hrs. Water Maint. Man - 2 at _____ \$ _____	
_____ Hrs. Garage Foreman _____ at _____ \$ _____	
_____ Hrs. Labor _____ at _____ \$ _____	
_____ Hrs. Compressor at _____ \$ _____	
_____ Trucking _____ \$ _____	
_____ Pav't Patch _____ \$ _____	
_____ \$ _____	
_____ \$ _____	
_____ \$ _____	
_____ \$ _____	
_____ \$ _____	
_____ \$ _____	

St. 14
 PI. 14
 Ave. No. 14

Name of Owner MICHAEL LAYDEN

Labor and Mat'l. Report 5-9-2002

