

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4" same	\$	-
1	Curb	Cock Valve T. S. & V.	3/4" oriseal	\$	1.92
1	Service Box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buffer Rdway		\$	1.82
29	Ft.	3/4 in.	Copper Galv Iron Cast Iron	Pipe at	\$ 5.22
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Couplings to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints at			\$	
	Leadite Joints at			\$	
	Hrs. Foreman at			\$	
9	Hrs. Chauffeur at	6.9 3/4		\$	6.19 1/2
3	Hrs. Tapper at	?		\$	2.06 3/4
3	Hrs. Labor at	6.2		\$	1.90
	Hrs. Labor at			\$	
1	Hrs. Compressor at	9.7 1/2		\$.88
	Compensation Ins.	3.2 1/3		\$.22
	Trucking			\$	1.00
	Builders Use of Water			\$	12.87
	Tap by Mellen			\$	
	2 Hole 3 x 5 + 3 x 6			\$	
	Made new Tap +			\$	
	Replaced Tubelay with Copper			\$	33.96
	5-2-63				
	by Lareau + Co.				

2113

St. _____
 Pl. _____
 Ave. No. 12

Name of Owner, Henderson,
 Home 5-2-63
 Renewed with Copper

Labor and Mat'l. Report Aug 5 19

4" Main Elev. of Main at tap 5'

Gate at ● Gate at ●

30' to MAIN

● Curb Box

TAX ID# 303.13-1-6