

LSM-5C-6-1-45

St. *Maple St*
 Pl. *34-98*
 Ave. No. *34-98*

Name of Owner *First Nat. Bank Drive-in*
Honeycutt Bank

Labor and Mat'l. Report *July 30* 19 *47*

Gate at ● *6* Main Elev. of Main at tap *5*

● Curb Box For Hose Connection

1" COP
2 1/2"

● Curb Box

Gate at ●

● Curb Box

36.5"
16.4"

See below

Labor and Mat'l. Report *July 30* 19 *47*

Name of Owner *First Nat. Bank Drive-in*
Honeycutt Bank

St. *Maple St*
 Pl. *34-98*
 Ave. No. *34-98*

LSM-5C-6-1-45

St. *Maple St*
 Pl. *34-98*
 Ave. No. *34-98*

Name of Owner *First Nat. Bank Drive-in*
Honeycutt Bank

Labor and Mat'l. Report *July 30* 19 *47*

Gate at ● *6* Main Elev. of Main at tap *5*

● Curb Box

See below

36.5"
16.4"

● Curb Box For Hose Connection

1" COP
5 1/2"

Labor and Mat'l. Report *July 30* 19 *47*

Name of Owner *First Nat. Bank Drive-in*
Honeycutt Bank

St. *Maple St*
 Pl. *34-98*
 Ave. No. *34-98*

