

**Labor and Materials**

1	Lead Connection	3/4"	\$
1	Curb Cock	"	\$
1	Service Box	(Short 3 1/2 x 4 1/2)	\$
	Old returned	(Long 4 1/2 x 6 1/2)	\$
		Buffalo	
1.7	Ft. " in. G. I. Pipe at		\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Coup	to in. at	\$
	Inc'g Coup	to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Cu. Yds. Br. Stone at		\$
	Cu. Yds. Sand at		\$
	Bags Cement at		\$
	Paving Brick	(Mack Red Asphalt) at	\$
2	Hrs. Foreman at		\$
1.8	Hrs. Common Labor at		\$
	Hrs. Mason at		\$
	Hrs.	at	\$
	Hrs.	at	\$
2.0	Builders' Use of Water		\$
	Truck	100	\$
		at	\$
		at	\$
		at	\$
	Total	\$ 20.36	

**Labor and Material Report** Apr 24 1928



Main Elev. of Main at tap 7.11  
 Gate at ● Gate at ●

Curb Box  
 Curb Cock is out of range  
 it shows shut off when  
 narrow. H  
 this tap 90 ft + 1/2 Main