

LABOR AND MATERIALS

1 Copper } Connection \_\_\_\_\_ \$  
 1 Lead }  
 1 Curb } Cock } 3/4 in. (H.A. 25) } \$  
           } Valve } (Copt. Cop)  
           } T.S. & V. }  
 1 Service box } Short 3 1/2 x 4 1/2 }  
 Old returned } Long 4 1/2 x 5 1/2 }  
                   } Buff or Rdway } \_\_\_\_\_ \$  
 27 Ft. 3/4 in. } Copper } Pipe at \_\_\_\_\_ \$  
                   } G.I. }  
                   } G.I. }  
 \_\_\_\_\_ Nipples \_\_\_\_\_ in. at \_\_\_\_\_ \$  
 \_\_\_\_\_ Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \_\_\_\_\_ \$  
 \_\_\_\_\_ Red'g }  
 \_\_\_\_\_ Inc'g } Coupl'gs \_\_\_\_\_ to \_\_\_\_\_ in. at \_\_\_\_\_ \$  
 \_\_\_\_\_ Union \_\_\_\_\_ in. at \_\_\_\_\_ \$  
 \_\_\_\_\_ Meter \_\_\_\_\_ in. at \_\_\_\_\_ \$  
 \_\_\_\_\_ Lead Joints at \_\_\_\_\_ \$  
 \_\_\_\_\_ Compound Joints at \_\_\_\_\_ \$  
 \_\_\_\_\_ Maintenance Foreman \_\_\_\_\_ \$  
 \_\_\_\_\_ Hrs. Water Maint. Man—1 at \_\_\_\_\_ \$  
 \_\_\_\_\_ Hrs. Water Maint. Man—2 at \_\_\_\_\_ \$  
 \_\_\_\_\_ Hrs. Garage Foreman \_\_\_\_\_ at \_\_\_\_\_ \$  
 \_\_\_\_\_ Hrs. Labor— \_\_\_\_\_ at \_\_\_\_\_ \$  
 \_\_\_\_\_ Hrs. Compressor at \_\_\_\_\_ \$  
 \_\_\_\_\_ Compensation Ins. at \$ \_\_\_\_\_ per C \_\_\_\_\_ \$  
 \_\_\_\_\_ Trucking \_\_\_\_\_ \$  
 \_\_\_\_\_ Pav't Patch \_\_\_\_\_ \$  
 \_\_\_\_\_ Tap Made By Beecher 4 G \_\_\_\_\_ \$  
 \_\_\_\_\_ O'head Sept. 25-1973 \_\_\_\_\_ \$  
 \_\_\_\_\_ \$

Ridge St. Ave. No. 220

Name of Owner  
 THOMAS CAMPBELL

Labor and Mat'l. Report Sept 25 1973

Ridge St. Curb Box  
 Hayt Ave

4" Main Elev. of Main at tap 5'

Gate at • Gate at •

• Curb Box

3/4" - 27' COPPER

TAX ID# 302.16-14-6 PL

LSM-5C-6-1-67