

**COUNTY FACILITIES COMMITTEE MEETING
AIRPORT AGENDA
June 24 2025**

Committee Members: BRUNO, Geraci, Conover, Diamond, Strough, Etu, and Thomas

- I. Committee Meeting Call to Order by Chair**
 - II. Approval of Minutes of Prior Committee Meeting**
 - III. Privilege of the floor and public comment**
 - IV. Action Agenda/New Business Items:**
 - V. Discussion Items**
 - Solar Farm Project Update
 - Airport PAPI Project Update
 - Airport Markings Update
 - Annual FAA Part 139 Inspection Update
 - VI. Referrals/Pending Items**
 - VII. Privilege of the floor and public comment**
 - VIII. Motion to Adjourn**
-



U.S. Department
of Transportation
**Federal Aviation
Administration**

Eastern Region, Airports Division

1 Aviation Plaza, Room 516
Jamaica, NY 11434-4809

EIR# 2025EA800080

June 18, 2025

Mr. Robin Mapp, C.M., ACE
Airport Manager
Floyd Bennett Memorial Airport
433-Queensbury Ave. – Rm. 201
Queensbury, NY 12804

**GFL – Floyd Bennett Memorial Airport
Compliance Letter/Close-out Letter – FY 2025
Annual Airport Certification Inspection**

Dear Mr. Mapp:

On June 16 and June 18, 2024, the Federal Aviation Administration inspected your airport's organization, systems, facilities, and procedures for compliance with 14 C.F.R. Part 139 for FY2025. This document is considered to be a Compliance/Close-out Letter, the discrepancy found during the inspection was also addressed during the inspection.

At the end of that inspection, you were advised of the following finding:

1. Runway Safety Areas 139.309(b)(1)

In the runway safety area at the approach end of Runway 1, between the runway end lights and the pavement of the runway there is a ground hog hole. Each runway safety area must be cleared and graded and have no potentially hazardous, ruts, humps, depressions, or other surface variations.

This discrepancy was addressed during the inspection and is now considered closed.



Floyd Bennett Memorial Airport was found to be in good repair, thanks to the dedication of the airport manager and the airport staff.

Thank you for the hospitality extended to me during my visit.

If you have any questions concerning the inspection, you may contact me at 908-581-5191 or via frank.loprano@faa.gov any time.

Sincerely,

A handwritten signature in blue ink that reads "Frank J. Loprano". The signature is written in a cursive style.

Frank J. Loprano
Lead Airport Certification Safety Inspector
Safety & Standards Branch
Airports Division

GFL Floyd Bennett Field
Recommendations
6/16/25 – 6/18/25

1. The perimeter fence in many areas appears to be overgrown. The airport staff are doing their best to work at keeping the fence clear of vegetation, but there are only two of them and the perimeter fence is miles long. It may be beneficial if the airport considers hiring a contractor to clear heavy vegetation from the fence line.
2. Airport staff should sign up to receive the latest Advisory Circulars and Cert Alerts via the website links below.
http://www.faa.gov/airports/resources/recent_advisory_circulars/
http://www.faa.gov/airports/airport_safety/certalerts/