LABOR AND MATERIALS Copper Lead Connection . Cock Valve T. S. & V. Short 3½ x 4½ Long 4½ x 5½ Buff-or-Rdway Service box Old returned Copper G. I. Pipe at C. I. Nipples in. at. ____to____in. at___ Bushings Red'g Inc'g Coupl'gs to in. at \$ Union in. at Meter____in, at____ Lead Joints at Compound Joints at _____Maintenance Foreman _____ Hrs. Water Maint. Man-1 at Hrs. Water Maint. Man-2 at Hrs. Garage Foreman at / Hrs. Labor at Hrs. Compressor at.... ____Compensation Ins. at \$____per C___ ____Trucking _ Pav't Patch O'head

	5
Hovey	St. Pl. Ave. No. 7
Name of Owner	
_ Chami	1908
Labor and Mat'l, Report	3-27 193/
= 9	N W
185-4-4	
38	13-1-70
	• Curb Box
	Elev. of Main at tap
Gate at	• Gate at
T WINTER	© Curb Box
San Park	J