

### LABOR AND MATERIALS

1	Copper Lead	Connection	<u>3/4"</u>		\$
1	Curb	Cock Valve T.S. & V.	<u>3/4 in.</u>	<u>Ori seal</u>	\$
1	Service box	Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff or Rdway			\$
25	Ft. <u>3/4</u> in.	Copper G.I. C.I.	Pipe at		\$
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Coupl'gs	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man-1	at			\$
	Hrs. Water Maint. Man-2	at			\$
	Hrs. Garage Foreman	at			\$
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.	at \$	per C		\$
	Trucking				\$
	Pav't Patch				\$
	<u>Tap by Gifford &amp; Co</u>				\$
	<u>10-24-63</u>				\$
	O'head				\$

