

Not Paid for

15-1951  
St Pt 2?  
Ave. No. 6

Name of Owner  
Caputo (Builder)

Labor and Mat'l. Report Oct 3 1950

35'8" 35'8" Curb Box

---

Gate at ● Gate at ●  
Tax Map # 303.9-11-2

12" Main Elev. of Main at tap 5'

---

41'1" 40'2" Curb Box

see below

---

Labor and Mat'l. Report Oct 3 1950

Name of Owner  
Caputo (Builder)

15-1951  
St Pt 2?  
Ave. No. 6

Not Paid for

15-1951  
St Pt 2?  
Ave. No. 6

Name of Owner  
Caputo (Builder)

Labor and Mat'l. Report Oct 3 1950

41'1" 40'2" Curb Box

see below

---

12" Main Elev. of Main at tap 5'

Gate at ● Gate at ●  
Tax Map # 303.9-11-2

---

1967.

35'8" 35'8" Curb Box

## LABOR AND MATERIALS

1	Copper <del>Lead</del>	{ Connection	3/4"		\$ 3.04
1	Curb	{ Cock Valve F. S. & V.	3/4" in.		\$ 3.54
1	Service box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway			\$ 4.70
2.6	Ft.	{ Copper C. I. C. I.	3/4 in.	Pipe at 35	\$ 9.10
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	{ Coupl'gs	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints at				\$
	Compound Joints at				\$
	Hrs. Water Maint. Man-1 at				\$
3	Hrs. Water Maint. Man-2 at		1.13		\$ 3.39
8	Hrs. Labor	at	1.02		\$ 8.16
	Hrs. Labor	at			\$
	Hrs. Compressor at				\$
	Compensation Ins. at	\$ 2.66 per C.			\$ 31
	Trucking				\$ 1.00
	Pav't Patch	E.Y.T. of Main			\$
	Tap by Moquin				\$
					\$
					\$
	O'head				\$
					\$ 33.21