2 0	
Labor and Materials	
Conney) 3	
Copper Connection	. s. 1.5D.
Curb Cock	s. 17P.
TS.S.V.	. \$ \ '. 2 Je
Old returned Long 4½x5½	s.1.5.4.
(Copper)	-
Cast Iron at	\$
Nipplesin, at	\$
Dodle	*************
Inc'g Couplingstoin.at	\$
Unionin. at	
Meterin. at	\$
Lbs. Br. Stone at	B
Lbs. Sand at	
Mack	
Paving Brick Red Asphalt at	
Lead Joints at	
Leadite Joints at	
7. Hrs. Common Labor at	1 -
16. Hrs. Common Labor at 45	.7.20
Hrs. Mason at	
Hrs. Masons Helper at\$	
Hrs. Compressor at\$	
Compensation Ins\$	
Trucking	2
water rantiawn.	۵
Total Sa	2873
Total \$	

134 3 Labor and Mate	
3 Plan	+ &t .
	7/
22' 11"	26' 5" Curb Box
Main	Elev. of Main at tap
Gate at	• Gate at
0/0/20	Carb Box