

Copy.

Ridge

St. Pt. Ave. No. 250

Name of Owner
Adirondack Dairy
(Borden's)

Labor and Mat'l. Report Dec 8 1954

6" Main

Elev. of Main at tap 5'

Gate at • Gate at •

Ridge

Curb Box

LSM-5C-6-1-67

Ridge

St. Pt. Ave. No. 250

Name of Owner
French Mt Lumber

Labor and Mat'l. Report 1980

6" Main

Elev. of Main at tap 6 1/2'

Gate at • Gate at •

TAX ID # 302.12-13-5

Curb Box

3/4" - 22' copper

LSM-5C-6-1-67

LABOR AND MATERIALS

1 Copper } Connection 6" X 4" Tapping Valve. \$
 Lead }
 1 Curb } Cock Valve } 4 in. Valve. \$
 } T.S. & V. }
 1 Service box { Short 3 1/2 x 4 1/2 }
 Old returned { Long 4 1/2 x 5 1/2 } \$
 { Buff or Rdway }
 24 Ft. 4 in. { Copper } Pipe at \$
 { C.I. }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g }
 Inc'g } Coupl'gs to in. at \$
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Compound Joints at \$
 Maintenance Foreman \$
 Hrs. Water Maint. Man—1 at \$
 Hrs. Water Maint. Man—2 at \$
 Hrs. Garage Foreman at \$
 Hrs. Labor— at \$
 Hrs. Compressor at \$
 Compensation Ins. at \$ per C \$
 Trucking \$
 Pav't Patch \$
 2-6" Lead Joints \$
 3- " " " \$
 Tap by Miller & Co \$
 O'head 12-8' 54. \$
 \$

LABOR AND MATERIALS

1 Copper } Connection 3/4 \$
 Lead }
 1 Curb } Cock Valve } 3/4 in. \$
 } T.S. & V. }
 1 Service box { Short 3 1/2 x 4 1/2 }
 Old returned { Long 4 1/2 x 5 1/2 } \$
 { Buff or Rdway }
 22 Ft. 3/4 in. { Copper } Pipe at \$
 { G. I. }
 { C. I. }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g }
 Inc'g } Coupl'gs to in. at \$
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Compound Joints at \$
 Maintenance Foreman \$
 Hrs. Water Maint. Man—1 at \$
 Hrs. Water Maint. Man—2 at \$
 Hrs. Garage Foreman at \$
 Hrs. Labor— at \$
 Hrs. Compressor at \$
 Compensation Ins. at \$ per C \$
 Trucking \$
 Pav't Patch \$
 Top Tressner & Co \$
 4/11/80 \$
 O'head \$
 \$