


**ENTITY INFORMATION**

	<b>Project Title:</b> Replace Roaring Branch Rd Retaining Wall	<b>Project Submission Date:</b> June 10, 2020 7:00 PM
	<b>Entity:</b> Stony Creek	<b>Contact:</b> Frank Thomas


**PROJECT INFORMATION**

<b>Project Priority:</b> High	<b>Project Type:</b> Replacement	<b>Is this Project in the Hazard Mitigation Plan?</b> Y	<b>Project Category:</b> Transportation
-------------------------------	----------------------------------	---	---

**Project Description:**  
 This 300'x15' retaining wall supports a town road and has a creek at its base. It is constructed of round boulders and is approximately 80 years old. 30' of the wall collapsed during a 2019 storm, but the whole wall is in need of replacement. A closed road creates a 6 mile detour for residents living beyond the wall. During the winter this detour becomes very difficult to travel and maintain.

**Comments:**  
 The town spent \$41,000 with JMT engineers for a retaining wall inspection and evaluation report. Two price estimates were produced to replace entire wall, each \$1,000,000. Their opinion is the wall will fail as it is constructed with round boulders in the 1940's and the soil has washed away and it's basically sitting on cobbles.

**Project Location:** Roaring Branch Road Stony Creek



Esri, NASA, NGA, USGS | Esri, HERE, Garmin, SafeGraph, METI/... Powered by Esri

**PROJECT PLANNING AND FINANCING**

<b>Estimated Cost:</b> \$1,100,000	<b>Potential Funding Source(s):</b>
<b>Has a Planning Study Been Completed?</b> Yes	<b>Useful Life:</b> 75 years

