


ENTITY INFORMATION



Project Name: Raw Water Main Mapping & Condition Assessment; Flow Meter & Valve Replacement

Project Update Date: June 26, 2026 11:25 AM

Entity: Glens Falls

Contact: Steve Gurzler

PROJECT INFORMATION

Project Category: Water

Project Type:
Improvement


Priority: Medium

Is this Project in the Hazard Mitigation Plan? No

Project Description:

The water mains bringing in raw water to the filtration plant need to be assessed as to their condition and ability to handle the growing demand. The exact location of the main needs to be mapped and located for inclusion into a water GIS system. It may need repairs or replacement. The flow meters and valves need to be replaced.

Project Phase: PreDesign
Comments:

Project Location: Coles Woods

PROJECT PLANNING AND FINANCING

Estimated Cost: \$125,000

Has grant funding for this project been received?

Useful Life:

Funding Source(s): Engineering Planning Grant - Raw Water
Main Mapping and Condition Assessment