

**ENTITY INFORMATION**



**Project Title:** Raw Water Main Mapping & Condition Assessment; Flow Meter & Valve Replacement

**Project Submission Date:** October 31, 2019 7:00 PM

**Entity:** Glens Falls

**Contact:** Steve Gurzler

**PROJECT INFORMATION**

**Project Priority:** Medium

**Project Type:** Improvement

**Is this Project in the Hazard Mitigation Plan?** N

**Project Category:** Water

**Project Description:**

The water mains bringing in raw water to the filtration plant need to be assessed as to their condition and ability to handle the growing demand. The exact location of the main needs to be mapped and located for inclusion into a water GIS system. It may need repairs or replacement. The flow meters and valves need to be replaced.

**Comments:**

**Project Location:** Coles Woods



**PROJECT PLANNING AND FINANCING**

**Estimated Cost:** \$125,000

**Potential Funding Source(s):**

**Has a Planning Study Been Completed?**

**Useful Life:**